


# Potato Drying

A simple but effective way of drying potatoes in boxes is offered by Welvent.

## The Fan

Small axial flow fans, are put onto a plywood board, and provided with a set of wheels and a handle to make them portable. Available in both single phase and 3 phase options.



Supply	Motor Power	Fan Output	Approximate Tonnage
Single Phase	1.1kw	8000	40
3 Phase	1.5kw	10000	50

Other sizes available - Based on 200cfm/tonne for potato drying



The boxes are stacked in two rows with a space of approximately 800mm between them. The space is covered with one of our special sheets and the fan is then positioned against the end of the gap and the air is extracted from the space. Note totally solid sided boxes will not work with this system.

**D  
r  
y  
i  
n  
B  
O  
X  
e  
s**